

FORM MR-AR
(Revised 2/2001)

3/8/04
TW

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple - Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1/2002 To (mo./yr.) 1/2003
 2. DOGM File Number (Mine No): A1021032
 3. Mine Name: Red Dome
 4. Mineral(s) Mined (or permitted to mine): _____
 5. Type of mine ☒ Surface Mine or ☐ Underground Mine
 6. Legal Description (Location of Lands Affected):
1/4, L. 14, 1/4, Section 22, Township 21S, Range 6W S. L. 21.
1/4, 1/4, 1/4, Section _____, Township _____, Range _____
1/4, 1/4, 1/4, Section _____, Township _____, Range _____
 7. Name of Operator or Company: Red Dome Inc.
 8. Permanent Street Address: 200 South 5865 West
City, State, Zip: Fillmore UT 84631
Phone: 435-743-8111 Fax: 435-759-9184
 9. Company Representative (or designated operator):
Name: Lee T. Miller
Title: General Manager
Business Address: 200 South 5865 West
City, State, Zip: Fillmore UT 84631
Phone: 435-743-8111 Fax: 435-759-9184
- ☒ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was there any mine related activity during the past year? Yes ☒ No ☐
2. If no - what was the last year of activity? _____
3. If yes - how much ore or mineral was mined? 18,059.58 tons

RECEIVED

MAR 05 2004

DIV. OF OIL, GAS & MINING

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.

BASIN SCOURING OPERATION

5. How much additional acreage was disturbed during the past year? 0

6. How much acreage was reclaimed during the past year? 5 AC ±

7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

FILL IN PITS GROUND LEAKED OVER BURTON (SOL)
REPLACED

8. What is the total disturbed acreage of entire project at years end? _____

9. Briefly summarize any mining and/or reclamation plans for the upcoming year.

BUSINESS WILL DRIVE

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. Additional Information - R647-4-121.2 and .3

1. The operator shall include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.
2. The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

LEE T MILLER

Title of Operator:

General Manager

Signature of Operator:

L T Miller

Date:

3-2-04

jb
o:\format\reports\WR-AR